

# CORNER RECORD


Document Number \_\_\_\_\_

SECTION 34, T. 23 N., R. 13 E., M.D.M.

County of Plumas

, California

Brief Legal Description LOT 19, DELLEKER SUBDIVISION UNIT NO 2



## CORNER TYPE

Government Corner

Control

N. \_\_\_\_\_

Meander

Property

E. \_\_\_\_\_

Rancho

Other

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey AUGUST, 1992

## COORDINATES (Optional)

N. \_\_\_\_\_

E. \_\_\_\_\_

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 1/2" I.P.'s as shown on Page 2, in record positions from which I SET THE Southwest Corner of LOT 19

A description of the physical condition of the monument as found and as set or reset: Southwest CORNER OF LOT 19 was missing, SET 5/8" REAR with Plastic CAP LS 2843

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on Dec. 22 1992.

Signed John W. Hauny L.S. or R.C.E. Number L.S. 2843



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Dec 22 1992 and examined

and filed Jan 20 1993.


Signed R. Tom Shantz Title C. Engineer



County Surveyor's Comment \_\_\_\_\_

LEGEND

- Found 1/2" I.P. with Plastic Plug RCE 13219
- Set 5/8" Rebar with Plastic Cap LS 2843



Delleker Subdivision Unit No. 2

Book 3 Maps Page 8

92041