


## CORNER RECORD

Document Number 100Portion of Section 6, T. 23 N., R. 14 E., M.D.M. County of Plumas, CaliforniaBrief Legal Description Southwest corners of Lots 66, 67, 68 and point of slope easement between Lots 68 and 69, Crocker Mountain Estates, 3 M 44

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner. Found 1/2" I.P. at most Southerly corner of Lot 69 and at point of slope easement between Lots 41 & 42 at record positions. All other corners which were missing fell on steep cut banks.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with aluminum cap LS 2843 at the Southwest corners of Lots 66, 67, 68, and point of slope easement between Lots 68 and 69. at record position between found corners as shown on sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on October 10, 1994.


Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11/2 1994 and  
 examined and filed 11/2 1994.

Signed Tom Stanton Title \_\_\_\_\_



County Surveyor's Comment \_\_\_\_\_

Lots 66, 67, 68 & 69  
Crocker Mountain  
Estates

Legend

- Set 5/8" rebar with Aluminum Cap LS 2843

