

## CORNER RECORD


Sec. ~~10~~<sup>15</sup> T 23 N R 11 E

Document Number \_\_\_\_\_

County of Plumas

, California

Brief Legal Description Southerly line of property shown on 2 RS 112



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey April 2, 1996

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1" I.P. monuments shown on 2 RS 112. Those monuments that had been destroyed by road maintenance were replaced with 5/8" rebar with aluminum caps stamped L.S.2843.

A description of the physical condition of the monument as found and as set or reset:

See attached drawing for condition of found monuments.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 10, 1994.

Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 5/6 1996 and  
examined and filed 5/9 1996.Signed R. Tom Shute Title C. Surveyor

County Surveyor's Comment \_\_\_\_\_

## LEGEND

- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843
- (R1) RECORD per 2 RS 112
- (R2) RECORD per 9 RS 131



200 100 0 200 400 600  
 1" = 200'

