

CORNER RECORD

Document Number


224

Section 12, T. 22 N., R. 12 E., M.D.M.

County of Plumas

, California

Brief Legal Description Parcel 4, 5 PM 41 and Parcel 1, 8 PM 48



CORNER TYPE

Government Corner Control

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey May 4, 2002

Elev. _____

COORDINATES
(Optional)Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/2 rebar with Plastic Cap as shown on attached sketch from which I reestablished missing corner.


A description of the physical condition of the monument as found and as set or reset: From found corners as shown on attached sketch I set 5/8" rebar with Aluminum Cap stamped LS 5620.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 20, 2002.

Signed John L. Owen L.S. 5620
John L. Owen

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 6 2002 and
examined and filed December 18 2002.Signed Tom Stanton Title Plumas County Surveyor

County Surveyor's Comment _____

S88.59' 00" W
41.91'

Found 1/2" rebar with
Plastic Cap LS 3297
per 8 PM 48

1" = 100'

668.24'
S0058'41"E

Muledeer Road
S43°23'08"E
475.99'

Parcel 1
8 PM 48

Corner missing set Aluminum
Cap stamped LS 5620

Parcel 4
5 PM 41

Found 1/2" rebar with
Plastic Cap LS 3297
per 8 PM 48

W,00'58.88"

549.86'