


CORNER RECORD

Document Number #227

Sec. 10, T.22N.R.12E. M.D.M.

County of Plumas

, California

Brief Legal Description Parcel 1 5 PM 84

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Feb. 10, 2003

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as indicated on attached sketch in good condition. Set S.E. corner
in original position.

A description of the physical condition of the monument as found and as set or reset: Found 3 corners as shown on Parcel Map, except the Northwest corner which had the tag missing.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Feb. 10, 2003.


Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 19 2003 and
examined and filed March, 6 2003.Signed R. Tom Stanton Title Plumas County Surveyor

County Surveyor's Comment _____

- FOUND 3/4" iron pipe LS 3297 or as indicated
- SET 5/8" Rebar & Aluminum Cap LS 2843



PARCEL 1 5 PM 84

Section 10, T.22N.R.12E
M.D.M.
Plumas County, Ca
Scale 1" = 50' Feb. 2003

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571