


CORNER RECORD

Document Number _____

City of _____

County of PLUMAS, California

Brief Legal Description Most Southerly Corner of Parcel 2, 7 PM 62, Sec. 9, T. 22 N, R. 12 E, M.D.M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey October 16, 1992

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Original corner was a 1/2" IP tagged LS 3297 per 7 PM 62, appeared to have been set on edge of ditch, which was probably destroyed when ditch was cleaned. Reestablished corner in record position from found 1/2" IP, tagged LS 3297, to North and found 1/2" Rebar (Plastic Cap RCE 15265 per 7 PM 62 missing) to West

A description of the physical condition of the monument as found and as set or reset: Set 5/8" Rebar

with Plastic Cap LS 2843 on edge of ditch in record position from found points.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Oct. 16 1992.

Signed John W. Hamby L.S. or R.C.E. Number L.S. 2843



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 19__ and examined and filed Oct 27 1992.

Signed R Tom Hunter Title County Engineer



County Surveyor's Comment _____

