


CORNER RECORD

Document Number 193

Section 10, T. 22 N., R. 13 E., M.D.M. County of Plumas, California

Brief Legal Description Lots 11 thru 13, Iron Horse Rancho Subdivision, 3 M 110



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey March 29, 2001

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 1" Square head bolts and iron pipes at record locations as shown on attached sketch from which I established missing corners.

A description of the physical condition of the monument as found and as set or reset: Found corners as shown on attached sketch from which I set 5/8" rebars with Aluminum Caps stamped LS 2843 in record positions as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 3, 2001.


Signed John W. Hamby L.S. 2843  
John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 18<sup>th</sup> 2001 and examined and filed May 2<sup>nd</sup> 2001.

Signed R. Tom Hunter Title County Surveyor



County Surveyor's Comment \_\_\_\_\_



1" = 100'

Set 5/8" rebar & Aluminum Cap LS 2843

Found 1 1/4" I.P.

Found 1" SQ. Head Bolt

Found 1" SQ. Head Bolt

181.15'  
N71°20'00"E

80.70'  
N71°20'00"E

106.30'  
S42°16'55"W

108.01'  
180.35'

72.34'  
S42°16'55"W

Found 1" SQ. Head Bolt

45  
3 M 110

S42°16'55"W  
184.63'

Found Aluminum Cap LS 2843

14  
3 M 110

S47°43'05"E  
300.00'

S46°07'06"E  
300.48'

Nothing Found or Set

N42°16'55"E  
150.00'

Found 1" I.P.

12  
3 M 110

S37°52'56"E  
318.50'

13  
3 M 110  
Set 5/8" rebar & Aluminum Cap LS 2843

S29°38'46"E  
323.12'

11  
3 M 110

10  
3 M 110

S21°24'36"E  
301.42'

Found 1" SQ. head bolt inside pipe

Δ=8°14'10"  
R=940.00'  
L=135.12'

Δ=8°14'10"  
R=940.00'  
L=135.12'

Δ=8°14'10"  
R=940.00'  
L=135.12'

Δ=1°35'59"  
R=940.00'  
L=26.25'

These two corners could not be set because there are power poles in their location.

Lots 11 thru 13  
Iron Horse Rancho  
Subdivision, 3 M 110

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571