


CORNER RECORD

Document Number 278

Section 34, T. 23 N., R. 13E., M.D.M. County of Plumas, California

Brief Legal Description Lot 4, DELLEKER SUBDIVISION UNIT 2, 3 M 8



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES

(Optional)
N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found most Westerly corner of Lot 3 and most Southerly corner of Lot 4 of 3 M 7
in record position from which I set the most Westerly corner of Lot 4 as shown
on attached sketch.

A description of the physical condition of the monument as found and as set or reset: The most Westerly corner
of Lot 3 was a 1/2" I.P. with Plastic Plug RCE 13219, the most Southerly corner of
Lot 4 was a 1/2" I.P. with Plastic Plug down inside and not legible. I set a 5/8"
rebar with Aluminum Cap LS 2843 for the most Westerly corner of Lot 4 in record
position as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 16, 2004.

Signed John W. Hamby L.S. 2843
John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Dec. 21st 2004 and
examined and filed January 3, 2005

Signed R. Tom Hunter Title Plumas Co. Engineer

County Surveyor's Comment _____

ARRIBA AVENUE

60'

Found 1/2" I.P. with Plastic Plug RCE 13219

S23°49'16"E

90.00'

Note:
All Bearings and Distances
are record per 3 M 7

Lot 3

1"=20'

Corner missing set 5/8" rebar with Aluminum Cap LS 2843

S23°49'16"E

90.00'

Lot 4

3 M 7

Found 1/2" I.P. with Plastic Plug not legible

Lot 5

04248