

NOTES:

ALL CORNERS SHOWN AND DENOTED AS A STD. U.S.F.S. MONUMENT ARE AS FOLLOWS:

A ALUMINUM PIPE, 2 $\frac{1}{4}$ " IN DIAMETER, 27 $\frac{1}{2}$ " IN LENGTH, WITH A MAGNET INSTALLED IN A BREAK OFF PLASTIC BASE AND A 3" ALUMINUM CAP WHICH HAS BEEN STAMPED WITH PROPER IDENTIFICATION FOR EACH MONUMENT LOCATION ACCORDING TO MANUAL OF INSTRUCTIONS FOR THE SURVEY OF THE PUBLIC LANDS OF UNITED STATES, 1973.

EACH PIPE IS SET A MOUND OF STONE PLACED AROUND.

BEARING TREES - DIAMETER MEASURED CHEST HEIGHT, SPECIES, MAGNETIC BEARING AND DISTANCE MEASUREMENT IN FEET (DIVIDE BY 0.66 TO CONVERT TO LINKS) ARE NOTED ON CORNER DESCRIPTIONS HEREON.

TREES ARE PROPERLY BLAZED AND SCRIBED ACCORDING TO MANUAL AND U.S.F.S. INSTRUCTIONS OR AS FOUND AND NOTED DIFFERENTLY.

MEASUREMENTS ARE TO GALV. NAIL IN CENTER SIDE ABOVE ROOT CROWN OR TREE CENTER.

CORNERS FOUND DENOTED AS A B.L.M. OR U.S.F.S. MONUMENT ARE A ALUMINUM OR IRON PIPE 2 $\frac{1}{4}$ " IN DIAMETER WITH EITHER A ALUMINUM OR BRASS CAP PROPERLY MARKED FOR CORNER AND SET WITHIN A MOUND OF STONE WITH BEARING TREES AS NOTED IN CORNER DESCRIPTIONS.

GOV'T NOTES ARE ORIGINAL GOV'T SURVEY NOTES - A.W. KEDDIE, 1870 IN SECTIONS 2, 10 AND 11, WM. MINTO, 1880 IN SECTION 35.

W.F. — White Fir

Gov't BT's — Bearing trees as described in Gov't Notes.

Y.P. — Yellow Pine

D.F. — Douglas Fir

S.P. — Sugar Pine

B.O. — Black Oak

CORNER DESCRIPTIONS

① Sec. Cor. 10 11 Remonumented 1970 B.L.M. Brass cap mon. BT's 12" White Fir with healed blaze S68°E 25.10 Found 10" Yellow Pine with healed blaze N43 $\frac{3}{4}$ W 43.60 Found 14" W.F. with healed blaze S 48 $\frac{1}{2}$ W 11.60 Found 8" Y.P. " " N 50 $\frac{1}{2}$ E 17.40 Found

GOV'T BT's

10" W.F. S67°E (39 lks) 25.74

10" W.F. S49°W (18 lks) 11.88

9" Y.P. N42°W (66 lks) 43.56

8" Y.P. N53°E (27 lks) 17.82

② W 1/16 Cor. Sec. II / Sec. 14 R.L.S. 5147 as per 6-R/S-82 Std. USFS BT's 17" Y.P. S72°E 11.60 Found Al. Cap Mon. 17" Y.P. N53 $\frac{1}{2}$ W 13.80 Found

③ 1/4 Cor. Sec. II / Sec. 14 R.L.S. 5147 as per 6-R/S-82 Std. USFS Mon. Reference monument to North found but not tied in Al. Cap during this survey

④ Sec. Cor. 11 12 as per 6-R/S-82 Std. U.S.F.S. Mon. Al. Cap

BT's 6" Cedar N17°E 19.05 Found

6" Cedar S19 $\frac{1}{2}$ E 14.10 Found

7" Y.P. with healed blaze S 35 $\frac{1}{2}$ W 33.65 Found

7" Y.P. " " N 63 $\frac{1}{2}$ W 33.35 Found

Gov't BT's

5" Cedar N 19° E (29 lks) 19.14

7" Y.P. N 62° W (51 lks) 33.66

6" Cedar S 19° E (21 lks) 13.86

7" Y.P. S 36° W (51 lks) 33.66

⑤ SW 1/16 Cor. Sec. II LS 3634

BT's 12" S.P. N 3° E 24.75

12" S.P. N 66° E 25.45

⑥ C-S-C 1/16 Cor. Sec. II LS 3634

BT's 7" D.F. N 10° W 38.80

8" B.O. N 88° E 22.49

⑪ Sec. Cor. 10 11 3 2 Remonumented in 1970 BLM Brass Cap Mon. BT's 18" B.O. with healed blaze Found S 8 $\frac{1}{4}$ W 20.6

27" Cedar with healed blaze Found S 67 $\frac{1}{2}$ E 11.9

8" B.O. with healed blaze Found N 30 $\frac{1}{4}$ W 19.9

60" S.P. with healed blaze Found N 16 $\frac{1}{2}$ E 48.4

Gov't BT's 25" Cedar S 67 $\frac{1}{2}$ E (17 lks) 11.2

53" S.P. N 16 $\frac{3}{4}$ E (71 lks) 46.86

18" B.O. S 9°W (32 lks) 21.12

8" B.O. N 29°W (30 lks) 19.80

⑫ 1/4 Cor. Sec. 2 / Sec. II LS 3634 Found rock mound with scribed post on steep to East appears to have slipped downhill S87°34'E 5.14

BT's 15" D.F. N 4°E 13.68

11" W.F. S 65°E 18.5

Fd. B.O. stump hole-tree is down and decayed S24 $\frac{1}{2}$ E 20.3

Fd. B.O. stump hole-tree is down and decayed N9 $\frac{1}{2}$ W 10.9

Gov't BT's 4" B.O. S 21°E (32 lks) 21.12

6" B.O. N 2 $\frac{1}{2}$ W (18 lks) 11.88

⑬ W-E 1/64 Cor. Sec. 2 / Sec. II LS 3634 BT's 7" Cedar S 29°E 6.0

9" Cedar S 78°W 34.5

⑭ W-E-E 1/256 Cor. Sec. 2 / Sec. II LS 3634 BT's 10" Y.P. S 2°E 3.78

14" Red Fir N 45°E 19.47

⑮ Sec. Cor. 2 11 12 LS 3634 Replaced Found 1/2" Rebar RCE 26870 As Per 5-R/S-60

BT's 30" burnt Fir stump N53 $\frac{1}{2}$ W 81.5 Found

60" S.P. stump S 36°E 85.5 Found

8" S.P. N 50°W 7.5

9" Cedar N 11°E 19.1

7" B.O. S 30°W 17.4

15" Y.P. S 45°E 9.0

Gov't BT's 22" Spruce N40 $\frac{1}{2}$ W (144 lks) 95.04

22" Cedar S 43°W (102 lks) 67.32

57" S.P. S 32°E (127 lks) 83.82

20" Pitch Pine N78 $\frac{1}{2}$ E (74 lks) 48.84

⑯ 1/4 Cor. Sec. 10 / Sec. 15 B.L.M. Brass Cap Mon. Remonumented 1970

BT's 36" Y.P. with partly open blaze S 54 $\frac{1}{2}$ E 11.4 Found

26" Y.P. with healed blaze S 79 $\frac{1}{2}$ E 33.9 Found

34" Y.P. with healed blaze N 50°W 28.4 Found

Gov't BT's 32" Y.P. S 51 $\frac{1}{2}$ E (16 lks) 10.56

30" Y.P. N 47°W (42 lks) 27.72

24" Y.P. S 83°W (51 lks) 33.66

⑰ W 1/16 Cor. Sec. 10 / Sec. 15 LS 3634

BT's 8" Y.P. N 33°W 13.82

7" D.F. S 62°W 19.70

⑱ Sec. Cor. 9 10 Remonumented in 1970 BLM Brass Cap Mon.

BT's 15" Cedar with partly open blaze S 79 $\frac{1}{2}$ E 8.9 Found

19" Y.P. S 38 $\frac{1}{2}$ E 5.1 Found

8" Cedar S 67 $\frac{1}{2}$ E 19.5 Found

30" Y.P. with healed blaze N 49 $\frac{1}{2}$ W 13.0 Found

Gov't BT's 26" Y.P. N 32°E (106 lks) 69.96

16" Y.P. S 35°E (7 lks) 4.62

28" Y.P. N 47°W (19 lks) 12.54

13" Cedar S 76°E (14 lks) 9.24

7" Cedar S 70°W (30 lks) 19.80

⑲ Prorated Cor. 1/4 Cor. Sec. 9 / Sec. 10 LS 3634 No evidence of original corner due to mining and logging activities in area. Corner position fits tie to top of ridge and ditch to North Gov't (8.75 chs.) 577.50 measured 580.6

⑳ BT's 11" Cedar N 46°W 23.08 6" Cedar S 17°E 4.35 Burton Creek North 44.5

㉑ N 1/16 Cor. Sec. 9 / Sec. 10 LS 3634 BT's 6" W.F. N 52°E 4.03

6" W.F. N 52°W 14.06

㉒ NW 1/16 Cor. Sec. 10 LS 3634 BT's 7" D.F. N 4°E 5.40

5" Cedar S 52°E 11.60

㉓ Sec. Cor. 9 10 LS 3634 Found a mound of stone replaced BT's 14" W.F. N 51°W 21.2

28" Cedar S 49 $\frac{1}{2}$ E 22.9

6" S.P. N 62°E 24.34

5" Y.P. S 40°W 52.34

Gov't BT's 6" Fir S 37 $\frac{1}{2}$ E (25 lks) 16.50

10" Fir N 46°W (29 lks) 19.14

㉔ 1/4 Cor. Sec. 3 / Sec. 10 B.L.M. Brass Cap Mon. Remonumented in 1970

BT's 16" W.F. with healed blaze Found N 8 $\frac{1}{4}$ E 3.2

16" Cedar S 54 $\frac{1}{2}$ E 2.2 Found

Gov't BT's 13" Fir N 15°E (4 lks) 2.64

13" Cedar S 53°W (4 lks) 2.64

㉕ C-E-E-W-C 1/256 Cor. Sec. 2 LS 3634 BT's 10" D.F. S 53°W 7.83

6" D.F. N 44°W 9.47

㉖ C 1/4 Cor. Sec. 2 LS 3634

BT's 7" B.O. N 62°E 7.45

10" Cedar S 76°W 10.92

CORNER DESCRIPTION CONTINUES ON SHEET 6

RECORD OF SURVEY FOR UNITED STATES FOREST SERVICE

Being Sections 2, 10 and 11 - T. 24 N. - R. 8 E. and Section 35 - T. 25 N. - R. 8 E. - M.D.B. Plumas National Forest Plumas Co., CA

August, 1984

 LIPPINCOTT-GUTH ASSOCIATES
ENGINEERS SURVEYORS PLANNERS
1007 BILLE ROAD PARADISE, CALIFORNIA 95969-0671
(916) 877-8877 877-4300

Sheet 5 of 6 Sheets