


1. The Basis of Bearings of this Survey is identical to that shown in Book 8 of Maps at page 74, Plumas County records.
2. This Record of Survey was prepared to reflect a Lot Line Adjustment for which a resolution is Recorded in Book 747 of Official Records at page 99.



Lots 130, 131 & 133, Unit 6 "CLOUD PAINTER"  
8 M 74


Note: all bearings, distances and curve data shown are record per Gold Mountain Unit 6 "CLOUD PAINTER", 8 M 74 and Unit 14 "CLOUDS REST", 8 M 107, except those shown with (R1 & R2) which are measured per Lot Line Adjustment 747 O.R. 99, and 789 O.R. 231.

#### LEGEND


- FOUND Rebar with Aluminum Cap LS 2843
- SET 5/8" Rebar with Aluminum Cap LS 2843
- Nothing found or set

(R1) Record per 747 O.R. 99  
(R2) Record per 789 O.R. 231

1. The Basis of Bearings of this Survey is identical to that shown in Book 8 of Maps at page 118, Plumas County records.
2. This Record of Survey was prepared to reflect a Lot Line Adjustment for which a resolution is Recorded in Book 789 of Official Records at page 231.



Lots 331 & 332, Unit 14 "CLOUDS REST"  
8 M 118



## RECORD OF SURVEY for Gold Mountain Ranch, Inc.

Lots 130, 131 & 133  
Unit 6, "CLOUD PAINTER", 8 M 74  
and  
Lots 331 and 332  
Unit 14, "CLOUDS REST", 8 M 118  
Gold Mountain Subdivision  
A portion of Sections 15 & 16  
T. 22 N., R. 13 E., M.D.M.  
Plumas County, ~ California  
Scale 1" = 100' January, 2000

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571