


CORNER RECORD

City of _____

Document Number _____

Brief Legal Description NE CORNER LOT 27, IRON Horse RANCHO SUB., SEC 10, T. 22N, R. 13E, MDM.

County of Plumas, California



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/2" Bolts per 3M 110 at NE Corner of lot 29, SE corner and NW corner and SW corner of lot 27, Set NE corner of lot 27 at Proportionate distance Between NE corner of lot 29 and SE corner of lot 27

A description of the physical condition of the monument as found and as set or reset: Set 5/8" Rebar with Plastic Cap LS 2843, monument is in drainage

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Nov. 6 1992.

Signed John W. Hamby L.S. or R.C.E. Number L.S. 2843



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1/5 1993 and examined and filed 1/5 1993.

Signed R. Tom Smith Title Co. Surveyor



County Surveyor's Comment _____



1" = 60'

Found 1/2" Bolt
per 3 M 110

Lot 29

Found 1/2" Rebar bearing
N 88°44'02" E, 0.65' at
distance shown

(Record) Record per 3 M 110

Lot 28

(N 88°44'02" E 400.00')
N 88°43'07" E

399.97'

Found 1/2" Bolt
per 3 M 110

Set 5/8" Rebar with
Plastic Cap LS 2843
at proportionate
distance

Lot 27

Iron Horse Rancho
Subdivision

Found 1/2" Bolt
per 3 M 110