

CORNER RECORD


Document Number _____

Section 11, T. 23N., R. 13 E., M.D.M.

County of Plumas

, California

Brief Legal Description NW Cor. Lot 77, Lake Davis Highlands Subdivision Unit No. 1,3 M 76



CORNER TYPE

Government Corner Control Meander Property Rancho Other

Date of Survey June 11, 1996

COORDINATES
(Optional)

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found 3/4" Iron Pipes, not tagged, for corners of Lots shown in attached sketch from which I reestablished the Northwest Corner of Lot 77

A description of the physical condition of the monument as found and as set or reset: Northwest Corner of Lot 77 was missing, set 5/8" rebar with Aluminum Cap stamped LS 2843 in record position from found 3/4" Iron Pipes as shown in attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 11, 1996.

Signed John W. Hamby L.S. 2843
John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10/15 1996 and
examined and filed 11/1 1996.

Signed R. Tom Shuster Title Co Surveyor



County Surveyor's Comment _____

83

Found 3/4" I.P.
not tagged,
Set tag LS 2843

78

84

49.37'
N15°08'40"W

109.63'
N15°08'40"W

Found 3/4" I.P.
not tagged,
Set tag LS 2843

Found 3/4" I.P.
not tagged,
Set tag LS 2843

81.58'
21.32'

20 10 0 20

1" = 20'

77

Lot 77, Lake Davis
Highlands Subdivision
Unit No. 1
Portion of Section 11,
T. 23 N., R. 13 E., M.D.M.
Plumas County, California
Scale 1"=20'

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(916) 832-5571

96026CR