

CORNER RECORD

Document Number 146

Section 6, T. 25 N., R. 12 E., M.D.M.

County of Plumas, California

Brief Legal Description Parcel W, per 5 PM 76

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey May 15, 1997

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found Southwest corner of Parcel M and most Westerly corner of Parcel W. Found angle corner in Parcel W lying in ground, had appeared to have been pushed out.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Caps for missing corners which were destroyed by 1997 flood. Reset found 1/2" I.P. lying in ground and tagged LS 2843. Also tagged found 1/2" I.P. being most Westerly Corner of Parcel W. Set 5/8" rebar and Aluminum Cap stamped LS 2843 for reference point to Witness Corner @ 12.93 feet as shown in attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 15, 1997.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Oct 6 1997 and examined and filed Nov 3 1997.

Signed R. Tom Sfomto Title Co Surveyor

County Surveyor's Comment _____



