

CORNER RECORD


Section 1, T.22N.R.16E. M.D.M.

Document Number _____

Brief Legal Description Lot 5 SUMMIT ACRES per 4 M 131

County of Plumas

, California



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey 6-11-'98

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 3/4" Iron Pipe, open. Record shows 3/4" I.P. tagged R.C.E. 8596.

Found SW cor Lot 5 and SE cor Lot 6. Set SE corner Lot 5 by single proportioning.

A description of the physical condition of the monument as found and as set or reset:

Monuments appear to be as shown on the Record Map, except tags must be inside pipes.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 18, 1998.

Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7/20 1998 and
examined and filed 7/31 1998.Signed R. Tom Shantz Title Plumas Co. Surveyor

County Surveyor's Comment _____

N 1/4 Cor Sec. 1
T 22 N R16 E

Fd. tag in stone
L.S. 3536

656.43' (R)
N00°26'19"E (R)

Fd. 3/4" I.P.

329.99' (R)
S89°37'17"E (R)

657.58' (R)
S00°26'19"W (R)

LOT 5

Fd. 3/4" I.P.

333.09' (M)
333.43' (R)

657.29' (R)
S00°08'20"W (R)

Set 5/8" rebar capped L.S.2843

331.47' (M)
331.79' (R)

Fd. 3/4" I.P.

N89°40'17"W (R)

S89°40'17"E (R)

LOT 5
SUMMIT ACRES
A portion of the NE 1/4 of Section 1
T. 22 N., R. 16 E., M.D.M.
Plumas County ~ California

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571

98049