


CORNER RECO

Document Number 166County of PLUMAS

, California

Brief Legal Description PARCEL 1 OF 2 PM 105

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey MAY 28, 1999

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS IN RECORD POSITION AS SHOWN ON ATTACHED SKETCH

A description of the physical condition of the monument as found and as set or reset:

CORNER LOCATION FELL IN ROAD. SET SPIKE TO SHOW CORNER LOCATION, AND SET REFERENCE POINT ON INTERSECTION OF LOT LINE WITH EDGE OF ROAD EASEMENT. R.P. IS A 5/8" REBAR WITH ALUMINUM CAP STAMPED L.S. 2843.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on (MAY 28), 1999.

Signed John W. Hamby L.S. 2843
John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7/12 1999 and
examined and filed 7/13 1999.

Signed R. Tom Hunter
Title C. Surveyor



County Surveyor's Comment _____

COOLED POUR
(Dense)

found rebar
LS 3297
per 8 PM 130

N26°55'38"W
30.02' per 8 PM 130

S75°45'20"W 187.34 (8PM130)
GUIDICI LANE 164.29 (2pm105)

N65°04'30"E
16.00' per 8 PM 130

Scale 1"=100'



PARCEL 1 OF 2 P.M. 105

S82°34'57"W
Set rebar with aluminum
cap LS 2843

32.73'

R.P.

found rebar
plastic cap
RCE 11173

148.47'
N16°08'02"E

79.84'
N18°13'42"E
Set spike

142.18'
N00°35'12"E

CHIPMUNK
ROAD

3

PARCEL 1
2 P.M. 105
SW 1/4 SEC. 12,
T22N R12E, M.D.M.
PLUMAS COUNTY
CALIF. MAY, 1999

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571