

CORNER RECORD


Document Number _____

Sec. 35 T. 23 N. R. 13 E.

County of PLUMAS

, California

Brief Legal Description Lots 9 thru 14 - Block 3 - West Portola per 4 RS 143.



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Mar. 22, 2000

Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/2" I.P. tagged L.S. 3297 and checked corners of Lots 9 thru 14, Block 3, West Portola as shown on 4 RS 143 and on attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Found 1/2" Iron Pipe tagged L.S. 3297 per 4 RS 143, bent. Replaced with 5/8" Rebar with aluminum cap stamped L.S. 2843 as shown on attached sketch.

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on March, 22, 2000.

Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received March 24 2000 and examined and filed April 20 2000.Signed R. Tom Shantz Title Co Surveyor

County Surveyor's Comment _____





1"=50'



Lots 9 - 14
Block 3
West Portola
per 4 RS 143

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571