


## CORNER RECORD

Document Number 181

Section 17, T. 24 N., R. 15 E., M.D.M.

County of Plumas

, California

Brief Legal Description Lot 69, Dixie Valley Properties Unit 1, Book 4 of Maps Page 5, Plumas Co. records

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
 Found 3/4" rebar at most Westerly corner of Lot 70 and found Plastic Cap RLS 2469 on right of way line of  
 Dixie Valley road in record position per 4 M 8, as shown in attached sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Cap stamped LS 2843 at most Westerly corner of Lot 69 and at angle point on Westerly line of Lot 69 in record position as shown in attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 10, 2000.


Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 9/27 2000 and  
 examined and filed 10/2 2000.


Signed R. Tom Stauffer Title C. Surveyor



County Surveyor's Comment \_\_\_\_\_



1" = 200'



Note: Bearings and distances are record per 4 M 8

00093cr