


## CORNER RECORD

Section 8, T.22N.R.12 E. I.D.M.

Document Number 198Brief Legal Description Lot 3 Plumas Eureka Estates Unit No. 2County of Plumas

California



## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey Sept. 10, 2001

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 1/2" rebar, in record positions as shown on 4 M 96, and as indicated on the attached sketch.

Restablished Northwest corner Lot 3, Northeast corner Lot 3, and Southeast corner Lot 3 from found 1/2" rebar.


A description of the physical condition of the monument as found and as set or reset:

most of the found points were in fair condition and location. The Southerly corner of Lot 3 was badly bent so we replaced it with a 5/8" rebar capped LS 2843.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept. 10, 2001.

Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received October 18, 2001 and examined and filed October 23, 2001.

Signed R. Tom Stanton Title County Surveyor

County Surveyor's Comment \_\_\_\_\_



- Found 1/2" rebar per 4 M 96.
- Set 5/8" rebar capped LS 2843.



LOT 3 PLUMAS EUREKA  
ESTATES UNIT No 2  
4 M 96

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571

Plumas County, California  
Sept. 2001 Scale 1" = 60'