


CORNER RECORD

Document Number 104

Section 36, T.23N. R.13E. M.D.M.

County of Plumas

, California

Brief Legal Description Portion Block 53 Second North Addition to Portola Townsite

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Jan 24, 2002

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown and described on attached sketch and as shown on 9 PM 140.

A description of the physical condition of the monument as found and as set or reset:


Found points as described and in good condition. Points set as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January 24, 2002.

Signed John L. Owen L.S. 5620
John L. Owen


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 11, 2002 and
examined and filed February 15, 2002.Signed R. Tom Shuster Title County Engineer

County Surveyor's Comment _____

- FOUND Rebar with Plastic Cap LS 2843
- SET 5/8" Rebar & Aluminum Cap LS 5620.
- FOUND point as described

(R1) RECORD per 9 PM 140



BLOCK 53
SECOND NORTH ADD.
TO PORTOLA TOWNSITE

BOOK A PAGE 30

PORTOLA PLUMAS Co. CALIFORNIA
Scale 1" = 50' January, 2002

02006

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571