

## CORNER RECORD


Document Number # 206

Section 34, T.23N.R13E. M.D.M.

County of Plumas

, California

Brief Legal Description Lot 50 Delleker Subdivision, Unit No. 2



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)Meander  Property 

N. \_\_\_\_\_

Rancho  Other 

E. \_\_\_\_\_

Date of Survey March 25, 2002

Zone \_\_\_\_\_ Datum \_\_\_\_\_


Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found original Lot Corner Monuments as indicated on attached sketch,


A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with Aluminum cap stamped L.S. 2843 at Southeast corner of Lot  
from found monuments.

## SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in  
conformance with the Land Surveyors' Act on March 25, 2002.Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 26<sup>th</sup> 2002 and  
examined and filed April 3<sup>rd</sup> 2002.Signed R. Tom Stanton Title P.C. Engineer

County Surveyor's Comment \_\_\_\_\_

corner falls in  
fence post



- Found monument per 3 M 9
- Set 5/8" rebar with aluminum cap LS 2843

01218

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571