

CORNER RECOR

Document Number


225

Sec.19, T.22N.R.13E. M.D.M.

County of Plumas

,California

Brief Legal Description Parcel 3 & Designated Remainder, 10 PM 77



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Nov. 2002

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Monuments found as indicated were in good condition.

A description of the physical condition of the monument as found and as set or reset:


Set 5/8" rebar capped L.S.2843 at locations shown on attached drawing.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Nov. 2002.

Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 12-5 2002 and
examined and filed December, 26 2002.Signed R. Tom Shantz Title P.C. Surveyor

County Surveyor's Comment _____

■ FOUND point as described
● SET 5/8" Rebar & Plastic Cap LS 2843
○ FOUND 1/2" REBAR, RCE 22836
○ FOUND 1/2" REBAR, LS 3297



A.P.N. 123-130-019&022



PARCEL 3 & DESIG. REMAINDER
 10 PM 77
 Por. Sec.19, T.22N.R.13E., M.D.M.
 PLUMAS COUNTY CALIF.
 Nov. 2002 Scale 1"=200'

Hamby Surveying Inc.
 P.O. Box 1209
 Portola, CA 96122
 (530) 832-5571

02254