

CORNER RECORD


Document Number

241

IN THE NW1/4 SEC. 36, T. 23 N., R. 16E., M.D.M.

County of PLUMAS, California

Brief Legal Description PARCEL 3 OF 5 PM 119



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey June 19, 2003

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


FOUND POINTS AS SHOWN AND DESCRIBED ON ATTACHED SKETCH AS SHOWN ON 5 PM 119.

A description of the physical condition of the monument as found and as set or reset:


FOUND POINTS AS DESCRIBED AND IN GOOD CONDITION. POINTS SET AS SHOWN ON ATTACHED SKETCH.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 30, 2003.

Signed John W. Hamby L.S. 2843
John W. Hamby


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received July 16, 2003 and
examined and filed August 5, 2003.Signed R. Joan Shuster Title County Surveyor

County Surveyor's Comment _____



1" = 200'



LEGEND

- FOUND 3/4" I.P. Tagged LS 2843
- SET 5/8" Rebar & Aluminum Cap LS 2843

03128

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571