

CORNER RECORD


Document Number 244

IN THE NW1/4 OF SEC. 1, T.22N., R.13E., M.D.M.

County of PLUMAS

, California

Brief Legal Description LOTS 17,18,19, & 20 OF 5 M 46



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey JULY 2003

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown and described on attached sketch and as shown on 5 M 46.

A description of the physical condition of the monument as found and as set or reset:


Found points as described and in good condition. Points set as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Aug 22, 2003.

Signed John W. Hamby L.S. 2843
John W. Hamby


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 27 2003 and
examined and filed September 10 2003.Signed R. Tom Stanton Title Plumas Co. Surveyor

County Surveyor's Comment _____



$$1'' = 60'$$



LEGEND

- FOUND point as described per 5 M 46.
- SET 5/8" Rebar & Aluminum Cap LS 2843

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571