


## CORNER RECORD

Document Number 256

Sec. 36 T.23N.R.13E. MDM

County of Plumas, CaliforniaBrief Legal Description Portion Block 71, 2nd. North Addition to Portola

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey Sept. 30, 2003

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points indicated in good condition as shown on attached sketch.


A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with aluminum cap stamped LS 2843 as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Oct. 6, 2003.

Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1/15/04 2004 and  
 examined and filed 1/27/04 2004

Signed R. Tom Skuntes Title Engineer




County Surveyor's Comment \_\_\_\_\_

- FOUND Rebar with Aluminum Cap LS 2843
- SET 5/8" Rebar & Aluminum Cap LS 2843
- FOUND 3/4" I.P.
- (R1) RECORD per 2 M 43

All distances are (R1) & Measured.



Scale 1" = 50'



Portion of Block 71  
Amended Re-Subdivision  
Second North Addition  
to Portola Townsite

03242

Hamby Surveying Inc  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571