


## CORNER RECORD

Document Number 257 ✓

Portion Section 4, T.23N.R.10E. MDM

County of Plumas, CaliforniaBrief Legal Description Portion Section 4, T.23N.R.10E

## CORNER TYPE

Government Corner  Control Meander  Property Rancho  Other Date of Survey October, 2003COORDINATES  
(Optional)

N. \_\_\_\_\_

E. \_\_\_\_\_

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

*Found USFS monuments as shown on the attached Sketch and on 10 RS 73, and  
set the monument in the position shown per 10 RS 73.*

A description of the physical condition of the monument as found and as set or reset:

*Found the USFS monuments in good condition and as shown on 10 RS 73.*

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on October 7, 2003.


Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1/15/04 2003 and 2004examined and filed 1/27/04 2003. 2004Signed R. Tom Slawter Title Engineer

County Surveyor's Comment \_\_\_\_\_

- FOUND USFS Aluminum Cap per 10 RS 73
- SET 5/8" Rebar & Aluminum Cap LS 2843
- (R1) RECORD per 10 RS 73



Scale 1" = 300'

Portion Section 4  
T.23N.R.10E MDM  
Plumas County, Ca.  
Scale 1" = 300'  
November 2003

03063-A

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571