


CORNER REC RD

Document Number 264

IN THE SW1/4 SEC 36, T23N., R16E., M.D.M.

County of PLUMAS, CaliforniaBrief Legal Description PARCEL 3, 5 PM 66010-130-034

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey DECEMBER, 2003

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND POINTS AS SHOWN AND DESCRIBED ON ATTACHED SKETCH AND AS SHOWN ON
5 PM 66 and 6 PM 67.

A description of the physical condition of the monument as found and as set or reset:

FOUND POINTS AS DESCRIBED AND IN GOOD CONDITION. POINTS SET AS SHOWN ON ATTACHED
SKETCH.


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on December 10, 2003Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 31 2004 andexamined and filed April 13, 2004.Signed R. Tom Shantz Title Engineer

County Surveyor's Comment _____



LEGEND

- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571