

CORNER RECORD


Document Num

269

A portion of N.E.1/4 Section 17, T.21N.R.9E. MDM

County of Plumas, California

Brief Legal Description Lot 108 - Laport Pines Country Club 2 M 71



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Sept. 11, 2004 Found

Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found all points indicated on the attached sketch in good condition and in proper location. Set a 5/8" rebar with aluminum cap stamped LS 2843 to replace the missing corner.

A description of the physical condition of the monument as found and as set or reset:

see statement above

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept 11, 2004.

Signed *John W. Hamby* L.S. 2843
John W. Hamby


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 9/22 2004 and
examined and filed 10/04 2004.Signed *R. Tom Stanton* Title _____

County Surveyor's Comment _____

- FOUND 1/2" rebar per 2 M 71
- FOUND 1 " Iron Pipe per 2 M 71
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Nothing found or set

All bearings and distances shown
are record per 2 M 71 and
measured.



Lot 108
La Porte Pines Country Club
A portion of Section 17,
T.21N.R.9E., M.D.M.
Plumas County, Ca.
Sept. 2004 Scale 1"=50'

04260

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571