


CORNER RECORD

Document Number 277

Section 1, T.22N.R.13E. MDM

County of Plumas, CaliforniaBrief Legal Description Lot 51 Ridgewood Subdivision Unit No 1, 5 Maps 45, 46

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey April 12, 2004

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
found corner monuments indicated in good condition and in record locations.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with aluminum cap LS 2843 at location indicated

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 12, 2004.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Nov. 1st 2004 and
 examined and filed November 29, 2004.

Signed Tom Smith Title Engineer

County Surveyor's Comment _____




- FOUND 1/2" Rebar with Plastic Cap LS 3297
- SET 5/8" Rebar & Aluminum Cap LS 2843

(R1) Record per 5 M 45

(M) Measured

A.P.N. 126-184-011



LOT 51

RIDGEWOOD SUBDIVISION
BOOK 5 MAPS 45 & 46
SECTION 1 T.22N.R.13E.
M.D.M.

M.D.M.

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571