


CORNER RECORD

Document Number 282

Portion NE 1/4 Section 36, T.23N.R.13E.

County of Plumas

, California

Brief Legal Description Lot 9 Block 50 Second North Addition to Portola Townsite
Book A Maps page 30.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey May 28, 2004

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found corners indicated in good condition. Found NE and SE corners of Lot 9 per corner record #200 destroyed by construction and replaced with rebar with Aluminum cap stamped LS 2843.

A description of the physical condition of the monument as found and as set or reset:
see note above.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 28, 2004.

Signed J W Hamby L.S. 2843
 John W. Hamby

3-22-05

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 22nd, 2005 and examined and filed March 24th, 2005.

Signed R Tom Stanton Title Engineer
Plumas County

County Surveyor's Comment _____




- FOUND Rebar with Plastic Cap LS 6051, per corner record 200.
- FOUND 5/8" rebar with cap LS 2843 per corner record 200.
- FOUND point as described
- SET 5/8" Rebar & Plastic Cap LS 2843
- (R1) per corner record # 200
- (R2) per A Maps 30



APN 125-186-007

Scale 1"=50'



Lot 9 Block 50
Second North Addition
Portola Townsite
A Maps 30

04135

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571