


CORNER RECORD

Document Number 295

Portion NE 1/4 Section 36, T.23N.R.13E.

County of Plumas, CaliforniaBrief Legal Description Lot 9 Block 50 Second North Addition to Portola Townsite
Book A Maps page 30.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey May 28, 2004

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found corners indicated in good condition. Found NE and SE corners of Lot 9 per corner record #200 destroyed by construction and replaced with rebar with Aluminum cap stamped LS 2843.

A description of the physical condition of the monument as found and as set or reset:
see note above.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 28, 2004.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received April 8th 2005 and
 examined and filed May 31, 2005.

Signed R. Tom Shute Title Engineer



County Surveyor's Comment _____

- FOUND Rebar with Plastic Cap LS 6051, per corner record 200.
 - FOUND 5/8" rebar with cap LS 2843 per corner record 200.
 - FOUND point as described
 - SET 5/8" Rebar & Plastic Cap LS 2843 (R1) per corner record # 200 (R2) per A Maps 30



Lot 9 Block 50
Second North Addition
Portola Townsite
A Maps 30

04135

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571