

## CORNER RECORD


Document Number 300

Section 24 T.24N.R.9E. MDM

County of Plumas

, California

Brief Legal Description Lot 1 Claremont Village No. 4 4 M 90



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey April 15, 2004

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as indicated in good condition

A description of the physical condition of the monument as found and as set or reset:  
Set points as indicated on attached sketch

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 15, 2004.

Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Dec. 8<sup>th</sup> 2004 and  
examined and filed August 8 2005Signed R. Tom Shantz Title County Surveyor

County Surveyor's Comment

- FOUND 1/2" rebar with Plastic Cap RCE 11173
- FOUND 1/2" Rebar with Plastic Cap LS 3297 per 12 RS 141.
- ❖ FOUND 1/2" Rebar LS 6051 per 12 RS 141.

- SET 5/8" Rebar & Plastic Cap LS 2843

- Nothing found or set

- Found 1/2" rebar

(R1) RECORD per 4 M 90

(R2) RECORD per 12 RS 141

(R3) RECORD per 5 PM 57

(R4) RECORD per 4 PM 108



LOT 1  
CLAREMONT VILLAGE No.4  
4 m 90  
Section 24, T.24N.R.9E. MDM  
Scale 1"=100' April, 2004

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571

