


## CORNER RECORD

Document Number 308

Portion of Section 36, T. 23 N., R. 13 E., M.D.M.

County of Plumas, State of California

Brief Legal Description Most Northerly Corner Lot 2, Parkside Terrace Subdivision No. One, 2 M 31

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey August 5, 2005

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 1" square head bolts at angle point in portion of subdivision labeled "NOT A PART" and at angle point in Lot 2. These appear to be what was set according to 12 RS 147. See attached sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Cap stamped LS 5620 at Northeast corner of Lot 2 in record position from found corners as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 5, 2005.

Signed John L. Owen L.S. 5620  
 John L. Owen



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Aug. 10<sup>th</sup> 2005 and examined and filed October 25 2005.

Signed Tom Stanton Title Plumas Co. Surveyor

County Surveyor's Comment \_\_\_\_\_



Bearings and distances shown  
are record per 2 M 31  
and measured



1" = 50'

MEADOW

WAY

60.00.

LOT 37  
2 M 31  
12 RS 147

Found 1" square head bolt  
accepted as corner, see Legend  
note per 12 RS 147

S35°59'W  
171.41'

NOT A PART  
2 M 31

Set 5/8" rebar with Aluminum  
Cap stamped LS 5620

S54°01'E  
64.83'

Found 1" square head bolt  
accepted as corner, see Legend  
note per 12 RS 147

LOT 2  
2 M 31

1200  
NO. 1 E. 6.

State

Highway

70

05130