

CORNER RECORD

311

COUNTY OF Plumas

T. 28 N

R. 8 E


Mount Diablo

MERIDIAN

CALIFORNIA

CORNER TYPE: GOVT CORNER MEANDER RANCHO

September 30, 2004

CONTROL OTHER 

Section 30

approximate location

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT


PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

The most Northerly corner of Lot 3, Block 2, LACC Unit 2, 1 Maps 67 was presumably destroyed by the placement of a concrete driveway. The corner was re-established using the found corners on Lot 3 and monuments found across the street on Lot 13, Block 7.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set chiseled "X" in concrete driveway.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) COUNTY OTHER
 ZONE ELEVATION NORTHINGS(Y) STATION STATION EASTINGS(X)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER
MY DIRECTION IN CONFORMANCE WITH THE LAND
SURVEYORS ACT ON September 30, 2004.


SIGNED

James Q. Eddy Jr.

L.S. or R.C.E. No. L.S. 4530

04-03-44

SEAL



COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED
AND EXAMINED AND FILED 10/25/04
BY: Robert T. Hunter
TITLE: Plumas Co. Engineer
DOCUMENT NO. 311

