


CORNER RECORD

Document Number

329

Section 10, T. 22 N., R. 13 E., M.D.M.

County of Plumas, California

Brief Legal Description Lot 89, Resubdivision of Iron Horse Rancho Subdivision, 3 M 110

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey August 1, 2006

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 1" sq. head bolts at Northeast corner of Lot 87, Northeast and Southeast corner of Lot 90 in record positions. Corners used to set Northeast corner of Lot 89 as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum cap stamped LS 5620 at Northeast corner of Lot 89 as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 16, 2006.

Signed John L. Owen L.S. 5620
 John L. Owen




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Nov. 08, 2006 and examined and filed November 22, 2006.

Signed R. Tom Shantz Title County Engineer

County Surveyor's Comment _____





Note: All bearings and distances are record per 3 M 110



1" = 60'