


CORNER RECORD

Document Number 335Portion of Section 6, T. 23 N., R. 14 E., M.D.M. County of Plumas, CaliforniaBrief Legal Description Most Northerly corner of Lot 72, Crocker Mountain Estates, 3 M 44

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 1-16-2007

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Northwest corner of Lot 59 per Corner Record # 98 which is the most Northerly corner of Lot 72 was destroyed by road work. Reestablished most Northerly corner of Lot 72 at record bearing & distance between Southwest corner of said Lot 59 and Northwest corner of Lot 60. Accepted 1/2" rebar with Aluminum Cap stamped LS 2843 for said Northwest corner of Lot 60.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with aluminum cap, stamped LS 5620, for most Northerly corner of Lot 72 as shown on sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January, 16, 2007.

Signed John L. Owen L.S. 5620
 John L. Owen



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received Jan. 22nd 2007 and

examined and filed 2007.

Signed R. Tom Hunter Title County Surveyor



County Surveyor's Comment _____



Lots 72
Crocker Mountain
Estates

06216