


## CORNER RECORD

Document Number 337

Portion of Section 16, T.23N., R.14 E. M.D.M. County of PLUMAS, California  
 Brief Legal Description LOT 174 OF GRIZZLY RANCH, UNIT 4 9 M 141



## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey January 15, 2007

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 5/8" Rebar with Aluminum Cap stamped LS 2843 per 9 M 141 to reestablish

Lot Corners as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" Rebar with Aluminum Cap stamped LS 5620 for corners to Lot 174 as shown on attached sketch

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January 15, 2007.

Signed John L. Owen L.S. 5620  
 John L. Owen



## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received Feb. 13<sup>th</sup>, 2007 and  
 examined and filed March 6<sup>th</sup>, 2007.

Signed R. Tom Shantz Title Plumas County Surveyor

County Surveyor's Comment \_\_\_\_\_



Note:  
All Bearings and distances are Record  
and Measured per 9 M 141



Lot 174

Grizzly Ranch, Unit 4  
9 Maps 141

Portion of Section 16, T.23N., R.14E  
M.D.M.

Plumas County, California

Scale: 1" = 40' January, 2007

LEGEND

- FOUND Rebar with Aluminum Cap LS 2843
- SET 5/8" Rebar & Aluminum Cap LS 5620

06030

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571