


CORNER RECORD

Document Number 351

Section 36, T. 23 N., R. 13 E., M.D.M.

County of Plumas, California

Brief Legal Description South 1/2 Block 5, Eastern Addition to Portola R.M. Book A, Pg. 27

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey February 2, 2007

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

*Found corners in Block 4, 6 and 13 as shown on attached sketch from which I set Lot corners in Block 5
as shown on attached sketch.*

A description of the physical condition of the monument as found and as set or reset: *Lot corners set are 5/8"*
rebar with Aluminum Cap stamped LS 5620 as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on April 15, 2007


Signed John L. Owen L.S. 5620
John L. Owen

5-31-07


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6/01 2007 and
examined and filed 6/25 2007.

Signed R. Tom Shuster
Title County Surveyor



County Surveyor's Comment _____



All bearings and distances shown for Blocks are record per 8 RS 9 & 10 RS 13

Legend



■ FOUND 5/8" rebar with Plastic Cap LS 2843 per 10 RS 13

● FOUND point as shown

○ SET 5/8" rebar with Aluminum Cap LS 5620


CR No. Corner Record

Block 11




All bearings and distances are record and measured.

4th Street



Block 12



Found 3/4" I.P.
tagged LS 6051
per CR 296

Found 3/4" I.P.
tagged LS 5620
per CR 321

05055cr

Block 13

S 1/2 Block 5
Eastern Addition to Portola
Portion Section 36,
T. 23 N., R. 13 E., M.D.M.

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571