

CORNER RECORD

Document Number 362

Section 21, T 23N, R14E

County of Plumas, CaliforniaBrief Legal Description Parcel 2 and 3, 6 PM 116

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey December 3, 2007

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found points shown on attached sketch in condition as indicated per 6 PM 116.

A description of the physical condition of the monument as found and as set or reset:


Set 5/8" Rebar with Aluminum Cap LS 5620 in record position shown on attached sketch per 6 PM 116.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 18, 2007.

Signed John L. Owen L.S. 5620
John L. Owen

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received Dec. 13th 2007 and
examined and filed Jan. 4th 2008.Signed R. Tom Shantz Title County Surveyor

County Surveyor's Comment _____



Bearings and Distances are Record
and Measured per Book 6 PM 116.

1" = 100'



Easterly line of Parcels 2 & 3
Book 6 Parcel Maps at Page 116
Situate in Section 21

Township 23 North, Range 14 East, M.D.M.

Plumas County ~ California
Scale 1" = 100' December, 2007

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571