

## CORNER RECORD


Document Num'r

373

T. 23 N., R 14 E. S. 16 MDM

County of Plumas, California

Brief Legal Description Lot 109, Grizzly Ranch Unit 2, 9 M 113



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey July 25, 2008

Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found Rebar with Plastic or Aluminum Caps, LS 2843, at locations shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" Rebar with Aluminum Cap at Westerly Corners of Lot 109  
as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in  
conformance with the Land Surveyors' Act on August 6, 2008.Signed John L. Owen L.S. 5620  
John L. Owen

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Aug. 11, 2008 and  
examined and filed 2008.Signed R. Tom Slauter Title County Surveyor  
RCE 30515

County Surveyor's Comment \_\_\_\_\_

All Bearings and Distances are Record and Measured per 9 M 113



1" = 50'

## LEGEND

- FOUND Rebar with Aluminum Cap LS 2843
- FOUND Rebar with Plastic Cap LS 2843
- ◐ SET 5/8" Rebar & Aluminum Cap LS 5620

