


## CORNER RECORD

Document Number 378

Section 35, T. 23 N., R. 16 E., M.D.M.

County of Plumas

, California

Brief Legal Description Parcel 4, per 12 Parcel Maps page 13. Plumas County records.

## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey 11-06-2008

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Set corners from found corners as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Set corners as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on November 11, 2008.


Signed John L. Owen L.S. 5620  
John L. Owen

11-1908

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Dec. 1<sup>st</sup> 2008 and  
examined and filed 12/22 2008.Signed Robert T. Hunter  
Robert T. Hunter RCE 30515  
Expires 3/31/2010  
County Surveyor's Comment \_\_\_\_\_Title County Surveyor

NOTE: All bearings and distances are record  
per 12 PM 13.



## LEGEND

- FOUND 1/2" Rebar with aluminum Cap LS 2843 per 12 PM 13
- FOUND 5/8" Rebar & Aluminum Cap LS 2843 per 12 PM 13
- SET 5/8" Rebar & Aluminum Cap LS 5620