


CORNER RECORD

City of Lake Almanor

Document Number 380

County of Plumas, California

Brief Legal Description Lot 15, Blk. 1, LACC #2 (R/M 1-67) Sec. 30, T28NR8E



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

3/4" i.p's. tagged RCE 6185 per R/M 1-67.

A description of the physical condition of the monument as found and as set or reset:

End monuments are old rusty pipes. Monuments set are new 1/2" rebars 24" long.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 9/10/09.

Signed Vernon H. Templeton P.L.S or R.C.E. No. 4647

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 17, 2009

and examined and filed Nov. 9, 2009

Signed R. Tom Spurlock P.L.S or R.C.E. No. RCE 30515

Title County Surveyor

County Surveyor's Comment _____



LEGEND


—●— FOUND 3/4" I.P. TAGGED RCE 6185 R/M 1-67.

—○— SET 1/2" REBAR W/ CAP STAMPED LS 4647,
EXCEPT AS NOTED.

SCALE : 1" = 100'

LAKE ALMANOR COUNTRY CLUB NO.2
BLOCK 1
R/M 1-67.

SET NAIL & TAG STAMPED LS 4647
IN SLATE PATIO.



SKETCH OF SURVEY