

CORNER RECORD

Document Number 384

S. 8, T. 22 N., R. 12 E. MDM

County of Plumas

, California

Brief Legal Description Lots 35, 36, 37, 39 & 40 Plumas Eureka Estates Unit 2, 4 M 96

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey September 7, 2010

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/2" Rebar, no tag, at Northwest and Southwest corners of Lot 40 and at the most Southerly corner of Lot 39 in good condition as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with Aluminum Cap LS 5620 for most Northerly corner of Lot 36 and the most Northerly corner of Lot 37 as shown on the attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 8, 2010.


Signed John L. Owen L.S. 5620
 John L. Owen



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 17 2010 and
 examined and filed October 20 2010.

Signed R. Tom Hunter Title County Surveyor



County Surveyor's Comment _____

LEGEND

- FOUND 1/2" Rebar, No tag, per 4 M 96
- Set 5/8" Rebar with Aluminum Cap LS 5620

Bearing and Distances are Record and Measured per 4 M 96

