

## CORNER RECORD


Document NumL

398

City of \_\_\_\_\_

County of Plumas, California

Brief Legal Description Located in Sec. 20 &amp; 21, T.23N., R.14E., M.D.M.



## CORNER TYPE

Government Corner  Control Meander  Property Rancho  Other 

Date of Survey 5-01-12

## COORDINATES (Optional)

N. \_\_\_\_\_

E. \_\_\_\_\_

Zone \_\_\_\_\_ NAD27  NAD83 

NAD83 Epoch \_\_\_\_\_

Elev. \_\_\_\_\_


Vert. Datum: NAD27  NAD83 Meas. Units Metric  Imperial Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found corners shown on 6 PM 116 as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset: From the corners found on attached sketch I set corner at record location shown on 11 RS 85 as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 14, 2012.

Signed  L.S. 5620  
John L. Owen


7-5-12

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received July 5 2012 and  
examined and filed July 14 2012.Signed  P.L.S. or R.C.E. No. 30512

Title Plumas Co. Surveyor

County Surveyor's Comment \_\_\_\_\_



## LEGEND

- FOUND 1/2" Rebar with Plastic Cap LS 15265 per 6 PM 116)
- SET 5/8" rebar with Aluminum Cap LS 5620
- Nothing found or set

