


CORNER RECORD

City of QUINCY

Document Number 411
County of PLUMAS, California

Brief Legal Description THE SE 1/4 OF SECTION 22, T24N, R8E, M.D.M.



CORNER TYPE

Government Corner

Control

Meander

Property

Rancho

Other

Date of Survey 8/26/14

COORDINATES (Optional)

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

IN PARCEL 3 OF 7PM 94, FOUND A 1/2" REBAR
WITH A PLASTIC CAP STAMPED LS 3297 AT THE
SOUTHERLY CORNER OF A LINE WHICH BEARS
N 0° 30' 20" W 141 51 FT.

A description of the physical condition of the monument as found and as set or reset: FOUND RUSTY
REBAR AND CRACKED. PLASTIC CAP WAS REPLACED
WITH A 5/8" x 24" REBAR WITH A 1 1/2" ALUMINUM
CAP STAMPED LS 6569. DISCARDED OLD REBAR AND CAP.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on AUGUST 26 2014

Signed John P. Schmidt L.S. or R.C.E. Number L.S. 6569

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 17 2014 and examined

and filed November 3 2014

Signed R. Tom Stauffer Title C. Surveyor

County Surveyor's Comment _____

