


# CORNER RECORD

City of QUINCY

Document Number 423

County of PLUMAS, California

Brief Legal Description BEGINNING AT POINT ON THE NORTH SIDE OF LAWRENCE STREET WHICH BEARS 588° EAST A DISTANCE OF 254.5 FEET FROM THE NORTHEAST CORNER CORNER TYPE OF CRESCENT AND COORDINATES (Optional) LAWRENCE ST.



Government Corner  Control   
 Meander  Property   
 Rancho  Other

Date of Survey DEC 16, 2016

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Vert. Datum: NGVD29  NAV88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE MAP ON OTHER SIDE

A description of the physical condition of the monument as found and as set or reset:


SEE MAP ON OTHER SIDE

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JANUARY 5, 2017.

Signed Richard Knoettgen  P.L.S. or R.C.E. Number L7794



## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received Jan. 5, 2017 and examined

and filed Jan. 24, 2017.

Signed R. Tom Shultz P.L.S. or R.C.E. Number RCE 30515

Title County Surveyor

County Surveyor's Comment \_\_\_\_\_






1 INCH = 40 FEET

### BASIS OF BEARING

THE BEARING OF S88°01'38"E FROM INFORMATION SHOWN  
IN BOOK 2 OF RECORDS OF SURVEY AT PAGE 130, BETWEEN THE RECOVERED  
MONUMENTS SHOWN HEREON.



A PARTIAL RETRACEMENT OF 2RS130  
A PARTIAL RETRACEMENT OF CORNER RECORD #197  
A FULL RETRACEMENT OF CORNER RECORD #393

FOR  
EPISCOPAL CHURCH OF NORTHERN CALIFORNIA

REPLACE MISSING MONUMENTS AT THE SW CORNER  
AND SE CORNER OF CHURCH PROPERTY  
ON LAWRENCE STREET  
JANUARY 5, 2017