

# CORNER RECORD

DOCUMENT NUMBER 408  
COUNTY OF PLUMAS, CALIFORNIA

CITY OF \_\_\_\_\_  
BRIEF LEGAL DESCRIPTION THE SOUTHEAST CORNER OF SECTION 29, T26N, R10E, M.D.M.

|    |    |
|----|----|
| 29 | 28 |
| 32 | 33 |

## CORNER TYPE

GOVERNMENT CORNER  CONTROL   
 MEANDER  PROPERTY   
 RANCHO  OTHER   
 DATE OF SURVEY: AUGUST 25, 2014

Corner - LEFT AS FOUND  FOUND AND TAGGED  ESTABLISHED  REESTABLISHED  REBUILT

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
 The land owner reported the corner common to Sections 28, 29, 32 and 33 MDB&M was dislodged during or after a major wild fire and a salvage logging operation. A skid road and logging operation removed the bearing trees and three of the existing Bearing Tree stumps. The corner monument was discovered by the owner and left in the vicinity. In 1999 I completed a field survey and filed a record of survey for the subject corner and a large area in the vicinity recorded as: (11-RS-55 TO 59). I was able to recover my original control survey in the vicinity and other evidence to relocate the subject corner.

A description of the physical condition of the monument as found and as set or reset:  
 I Reset the original monument at the record position and established four new reference monuments consisting of #5 rebars with RCE 29700 tags attached.  
 I stamped my "RCE29700" licence and "2014" to the old BLM monument cap. The monument is a brass capped steel pipe 30 inches long. The monument is set in the shoulder of a skid road with the cap 8 inches above ground level. I constructed a 36 inch diameter stone mound to the top of the pipe. I Found and tied a burned flush cut white fir stump (but no evidence of nails or blaze) 16" diameter at the base North 49° 49' East, 30.3 feet when measured to a 60d spike set at the center of the ring count. The recorded bearing in 1999 was North 49° 46' East, 30.3 feet. I left all four new reference monuments with 24 inch diameter stone mounds and 6 foot long metal stakes with appropriate signs. See sketch on reverse.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 26, 2014.

Signed [Signature] R.C.E. Number 29700



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 20, 2014 and examined and filed November 3, 2014.

Signed R. Tom Shinto Title Co. Surveyor



T. 26 N., R. 10 E., M.D.M.

