


CORNER RECORD

Document Number 409

City of QUINCY

County of PLUMAS, California

Brief Legal Description 78M 94 THE SE 1/4 OF SECTION 22, T24N R8E, M.D.M.



CORNER TYPE

**COORDINATES
(Optional)**

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8/26/2014

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

IN PARCEL 3 OF 78M 94 FOUND A 1/2" REBAR WITH PLASTIC CAP MARKED LS 3297 AT THE WESTERLY CORNER OF A LINE WHICH BEARS N 89° 41' 08" E 332.59 FT.

A description of the physical condition of the monument as found and as set or reset: FOUND RUSTY REBAR AND CRACKED PLASTIC CAP WAS REPLACED WITH A 5/8" x 24" REBAR WITH A 1/2" ALUMINUM CAP STAMPED L.S. 6569. DISCARDED OLD REBAR AND CAP.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on AUGUST 26 2014

Signed John P. Schmidt L.S. or R.C.E. Number LS. 6569



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 17 2014 and examined

and filed November 3 2014

Signed R. Tom Hunter Title Co. Surveyor



County Surveyor's Comment _____

