


CORNER RECORD

Document Number 412

City of Quincy

County of PLUMAS, California

Brief Legal Description THE SE 1/4 OF SECTION 22, T24N, R8E, M.D.M.



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8/26/14

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

IN PARCEL 3 OF T8M94, FOUND A 1/2" REBAR WITH PLASTIC CAP MARKED LS 3297 AT THE NORTHERLY CORNER OF A LINE WHICH BEARS NORTH 145.35 FT.

A description of the physical condition of the monument as found and as set or reset:

FOUND RUSTY REBAR AND CRACKED PLASTIC CAP WAS REPLACES WITH A 5/8" x 24" REBAR WITH A 1/2" ALUMINUM CAP STAMPED LS6569. DISCARDED OLD REBAR AND CAP.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on AUGUST 26 2014

Signed John P. Schmidt L.S. or R.C.E. Number LS 6569



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 17 2014 and examined and filed November 3 2014

Signed R Tom Hunter Title Co. Surveyor



County Surveyor's Comment _____

