

## CORNER DESCRIPTIONS

- 34 C-W-E-C 1/64 Cor. Section 2 LS 2780  
BT's 12" B.O. S 42 $\frac{1}{2}$ ° E 18.60  
11" W.F. N 28° E 45.00
- 35 1/4 Cor. Sec. 2 / Sec. 1 Remonumented 1970 B.L.M. Brass Cap Mon.  
BT's 11" D.F. with healed blaze N60 $\frac{1}{2}$ °E 19.3 Found  
5" D.F. " " " S89 $\frac{1}{2}$ °W 2.9 Found  
Gov't BT's  
10" D.F. N 64° E (29 lks) 19.14  
4" D.F. N 88 W (5 lks) 3.30
- 36 C-S-N-C 1/64 Cor. Sec. 2 LS 3634  
BT's 6" B.O. S 30° W 4.50  
12" D.F. S 63° E 4.58
- 37 SW-NE 1/16 Cor. Sec. 2 LS 2780  
BT's 11" W.F. N73°E 7.4  
8" Cedar N19°W 26.1
- 38 1/4 Cor. Sec. 34 / Sec. 3 LS 2780  
Found rotted Oak post in mound of stone  
at base of steep slope- flat to East- Fits Gov't notes  
Remonumented with std. monument  
BT's 26" S.P. with healed blaze S 36° E 33.0 Found  
40" S.P. stump N 57° W 27.7 Found  
10" W.F. S 5° W 17.83  
10" W.F. N 78 E 10.75  
Gov't BT's  
7" S.P. S 32° E (50 lks) 33.00  
45" S.P. N 58° W (42 lks) 27.72
- 39 Sec. Cor.  $\frac{34}{3}$  |  $\frac{35}{2}$  LS 2780 Prorated corner  
No evidence of original corner  
BT's 7" D.F. S 20° E 20.94  
6" Cedar S 32° W 14.95  
9" D.F. N 59° W 14.42  
7" D.F. N 12° E 17.64
- 40 1/4 Cor. Sec. 35 / Sec. 2 Remonumented in 1970 B.L.M. Brass  
BT's 9" S.P. N 21° E 16.0 Found Cap Mon.  
8" S.P. with healed blazed S 28° W 22.5 Found  
Gov't BT's  
9" S.P. N 24° E (24 lks) 15.84  
8" S.P. S 30° W (34 lks) 22.44
- 41 W-E-E 1/256 Cor. Sec. 35/Sec. 2 LS 2780  
BT's 6" Cedar S 24° W 9.30  
11" D.F. West 9.35
- 42 E-E 1/64 Cor. Sec. 35/Sec. 2 LS 2780  
BT's 7" B.O. S 4° E 13.88  
7" Cedar N 70° E 31.99
- 43 Sec. Cor.  $\frac{35}{2}$  |  $\frac{36}{1}$  Remonumented in 1970 B.L.M. Brass Cap Mon.  
BT's 10" D.F. with healed blaze N 73° W 27.6 Found  
6" B.O. " " " N 56° E 4.0 Found  
7" Cedar S 53 $\frac{1}{2}$ ° E 47.8 Found  
24" Y.P. stump S 4 $\frac{1}{2}$ ° W 13.9 Found  
5" Cedar S 38 $\frac{1}{2}$ ° W 11.2 Found  
Gov't BT's  
6" B.O. N 57° E (6 lks) 3.96  
7" Cedar S 51° E (72 lks) 47.52  
6" Cedar S 43° W (17 lks) 11.22  
8" D.F. N 70° W (43 lks) 28.38
- 44 C-S-SW-SE 1/256 Cor. Sec. 35 LS 2780  
BT's 7" D.F. S 50° W 9.65  
7" D.F. N 66° W 15.30
- 45 SW-SE-SE 1/256 Cor. Sec. 35 LS 2780  
BT's 6" D.F. S 30° W 21.33  
8" Cedar S 76° W 8.93
- 46 C-W-SW-SE 1/256 Sec. 35 LS 2780  
BT's 7" S.P. S 27° W 5.6  
8" Y.P. N 87° W 30.35
- 47 SW-SE 1/64 Cor. Sec. 35 LS 2780  
BT's 6" Cedar S 20° W 16.18  
7" Cedar S 86° W 33.90
- 48 C-S-SE 1/64 Cor. Sec. 35 LS 2780  
BT's 5" W.F. N 69° E 25.50  
6" B.O. N 24° E 16.48
- 49 SE-SE 1/64 Cor. Sec. 35 LS 2780  
BT's 6" D.F. S 41° E 5.24  
10" D.F. N 38° W 15.30
- 50 C-N-S-S-C 1/256 Cor. Sec. 35 LS 2780  
BT's 6" Cedar S 31° E 15.10  
6" Cedar S 42° W 12.49
- 51 NW-SW-SE 1/256 Cor. Sec. 35 LS 2780  
BT's 7" Y.P. S 76° W 20.12  
8" D.F. S 15° W 29.20
- 52 C-S-C 1/16 Cor. Sec. 35 LS 2780  
BT's 7" Cedar N 46° W 18.20  
8" Cedar N 66° E 6.55
- 53 SE 1/16 Cor. Sec. 35 LS 2780  
BT's 10" W.F. N 50° W 18.46  
16" D.F. S 85° E 17.25
- 54 1/4 Cor. Sec. 34 / Sec. 35 LS 2780 Prorated corner.  
Found no evidence of original corner.  
BT's 8" Fir S 8° E 37.2  
10" Fir S 45° W 44.5
- 55 1/4 Cor. Sec. 35 / Sec. 36 LS 2780  
Found 12" x 8" x 5" Stone loose in mound of stone  
Replaced with std. monument.  
BT's 30" S.P. stump with portion of blaze N 74° W 11.2 Found  
11" D.F. S 54° E 20.36  
7" D.F. S 14° W 19.14  
Gov't BT's  
12" S.P. N 73 $\frac{1}{2}$ ° W (17 lks) 11.22  
6" S.P. S 81 $\frac{1}{4}$ ° E (8 lks) 5.28  
Gov't cor. 12" x 8" x 5" granite stone
- 56 Sec. Cor.  $\frac{27}{34}$  |  $\frac{26}{35}$  LS 2843 Set in 1981 U.S.F.S. Al. cap mon.  
BT's 36" Cedar N 80 $\frac{1}{2}$ ° E 33.40 Found  
6" Maple stump S 29° E 39.4 Found  
12" Fir S 27° W 50.3 Found  
8" Fir N 74° W 17.8 Found  
6" Maple N 49 $\frac{1}{2}$ ° W 22.7 Found  
Gov't BT's  
22" Cedar N 81° E (51 lks) 33.66  
6" B.O. S 27° E (57 lks) 37.62  
6" S.P. S 51 $\frac{1}{2}$ ° W (43 lks) 28.38  
4" B.O. N 56° W (34 lks) 22.44
- 57 1/4 Cor. Sec. 26 / Sec. 35 LS 2780  
Found 20" x 14" x 3" stone in mound of stone.  
Replaced with std. monument  
BT's 26" Fir stump S 34° W 9.1 Found  
20" Fir N 45 $\frac{1}{2}$ ° W 40.9 Found  
6" Live Oak S 63° E 21.00  
Gov't BT's  
12" Red Fir N 35 $\frac{1}{2}$ ° W (63 lks) 41.58  
42" Red Fir S 56 $\frac{1}{2}$ ° W (15 lks) 9.90
- 58 Witness Corner LS 2780  
BT's 6" D.F. N 77° W 40.20  
8" Cedar S 52° W 52.55
- 59 Sec. Cor.  $\frac{26}{35}$  |  $\frac{25}{36}$   
Found blazed 16" Fir with stones around base. (Gov't 6" Balsam Fir)  
Witness corner bears N 89° 27' 37" W 3.07  
BT's 18" S.P. S 37 $\frac{1}{2}$ ° E 18.1 Found  
38" Fir N 42° E 12.1 Found  
Gov't BT's  
12" Fir N 39 $\frac{1}{2}$ ° E (18 lks) 11.88  
9" Fir S 31 $\frac{1}{2}$ ° E (27 lks) 17.82  
36" Cedar S 84 $\frac{1}{2}$ ° W (21 lks) 13.82  
15" Cedar N 82 $\frac{1}{2}$ ° W (100 lks) 66.00

# RECORD OF SURVEY

FOR

## UNITED STATES FOREST SERVICE

Being Sections 2, 10 and 11 - T. 24 N. - R. 8 E. and  
Section 35 - T. 25 N. - R. 8 E. - M.D.B.  
Plumas National Forest Plumas Co., CA

August, 1984



**LIPPINCOTT-GUTH ASSOCIATES**

ENGINEERS SURVEYORS PLANNERS  
1007 BILLE ROAD PARADISE, CALIFORNIA 95969-0671  
(916) 877-8877 877-4300

Sheet 6 of 6 Sheets