


NORTH  
1" = 40'

LEGEND

- ( ) Record per 1 PM 32
- (x) Fd 1/2" Rebar per 2 PM 29 tagged RCE III73
- (o) Fd. 3/4" I.P. per 1 PM. 32 tagged RCE III73 or as noted
- (•) Set 1/2" Rebar RCE 22836
- I.D.I.P. Inside Diameter Iron Pipe
- (+) Record per 2 PM 29



LOCATION MAP  
T24N, RIOE, Sec. 18 MDMB


**SURVEYOR'S STATEMENT**

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors Act at the request of Henry J. and Betty N. Klement in Oct. 1987.

*Clifford R. Brown*  
Clifford R. Brown RCE 22836

NOTES

- This Record of Survey was prepared to reflect a Lot Line Adjustment for which a resolution is recorded in Book 485 of Official Records at page 108-109.



**COUNTY SURVEYOR'S STATEMENT**

This map has been examined in accordance with Section 8766 of the Land Surveyor's Act this 5<sup>th</sup> day of August, 1988. This survey does not constitute a subdivision under Division 2 of Title 7 of the Government Code.

*Lawrence J. Brock*  
Lawrence J. Brock RCE 13528

**COUNTY RECORDER'S STATEMENT**

Filed this 5<sup>th</sup> day of August, 1988 at 10:53 A.M. in Book 8 of Records of Surveys, at page 34, at the request of the County Engineer.

Fee \$ 5.00

ILA DIGGS  
County Recorder

File No. 1000

*Matthew Williams*  
By Deputy

**RECORD OF SURVEY**

for

Henry J. and Betty N. Klement  
Rt. 1 Box 94  
Quincy, CA. 95971 (916) 283-2147

Within Section 18, T24N, RIOE MDMB  
north of East Quincy, Plumas County, California

Engineer: Cliff Brown Engineering & Survey  
Rt. 1 Box 480 B  
Quincy, CA. 95971 (916) 283-3959